

# Greeter Falls Area Trail Improvement Program

## Trail System Assessment August, 2022

-  Condition: good to fair (minor repairs?)
-  Condition: fair to poor, but could possibly be easily rerouted onto adjoining roadbed
-  Condition: fair to poor, requiring extensive repair; not easy to reroute
-  Condition: poor; likely requiring extensive reconstruction or reroute
-  Condition: poor to very poor in places, with sections requiring rebuild utilizing stonework or other structural construction
-  Condition: bad, dangerous or nonexistent, requiring complete rebuild using structural and/or stonework solution
-  Newly built or rerouted trail

